Smt. Kavitha Singh
Mob : 9964702826

Samrudhi Ground Water Consultant

#46, Gamgamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore - 03.

Ref. :.....

Date :...12/03/24.....

REPORT ON GROUND WATER INVESTIGATION

Name AEE BBMP YELAHANKA

Address Ward no-201

Location 3rd Cross Akash Vihar Layout

Topography Normal

Soil Type Red Soil

Rock Type White

Depth 150ft

Casing 350

Yield 6

Aqufers 2 ½"

Remarks –

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ...

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Samrudhi Ground Water Consultant
46, Gamgamma Temple Street,
Near Gangamma Temple,
Malleshwaram, Bangalore
Smt. Kavitha Singh
Water Diviner

...nsultants@gmail.com

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 1137

Date : 15/03/24

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka. Satelite Town Sub Division BBMP Blore-64

2. Well Location : 3rd Cross Akash Vihar Layout

3. Total Well Depth / Drilled in Ft. : 1400 -1500

4. Casing Erected in Ft. : 300 - 350

5. Water Struck at the Depth of : 1500

6. Total Yield (Measuring method "V" Norch : 6 " / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

8. At the Depth of : 1500

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Manager / Proprietor

Smt. Kavitha Singh
Mob : 9964702826

Samrudhi Ground Water Consultant

#46, Gamgamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore - 03.

Ref. :.....

Date :....12/03/24.....

REPORT ON GROUND WATER INVESTIGATION

Name AEE BBMP Yelahanka

Address Hard no - 01

Location Burial Ground, Srinivasapura, YNK

Topography Normal

Soil Type Red

Rock Type Schist

Depth 1250

Casing 300

Yield 6"

Aqufers 2"

Remarks —

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... **ನಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ...**

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Samrudhi Ground Water Consultant
46, Gamgamma Temple Street,
Near Gangamma Temple,
Malleshwaram, Bangalore - 03

Smt. Kavitha Singh
Water Diviner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 1131

Date : 25/03/24

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite town Sub Division BBMP Bldg -64

2. Well Location : Burial Ground, Srinivasapura. Yelk

3. Total Well Depth / Drilled in Ft. : 1250

4. Casing Erected in Ft. : 300

5. Water Struck at the Depth of : 1250

6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

8. At the Depth of : 1250

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report. I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Asst. Executive Engineer
Yelahanka Sub. Divisor
(BBMP Ynk. Zn)
Yelahanka, Bangalore

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Smt. Kavitha Singh
Mob : 9964702826

Samrudhi Ground Water Consultant

#46, Gamgamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore - 03.

Ref. :.....

Date :.....12/03/24.....

REPORT ON GROUND WATER INVESTIGATION

Name AEE BBMP YELAHANKA

Address Ward no -0201

Location KEB Layout HAROHALLI Rajankunte Yelahanka

Topography Normal

Soil Type Red

Rock Type Black

Depth 1400

Casing 250 - 300

Yield 6"

Aqufers 2 1/2"

Remarks -

Note : The Survey was carries out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it...ನೀರನ್ನು ಉಳಿಸಿ, ಮರಗಳನ್ನು ಬೆಳೆಸಿ...

Asst. Executive Engineer
Yelahanka Sub Divison
(BBMP Yhk. Zn)
Yelahanka, Bangalore

Samrudhi Ground Water Consultant
#46, Gamgamma Temple Street,
Near Gangamma Temple,
Malleshwaram, Bangalore - 03.
Smt. Kavitha Singh
Water Diviner

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

BOREWELL COMPLETION REPORT

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Mobile : +91 9342202932 / 9343202932

No. : 1126

Date : 15/04/24

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer Yelahanka Satellite Town Sub Division BBMP Bloreagy

2. Well Location : KEB layout Harohalli Rajakunte YNK

3. Total Well Depth / Drilled in Ft. : 1400

4. Casing Erected in Ft. : 250 -300

5. Water Struck at the Depth of : 1400

6. Total Yield (Measuring method "V" Norch : 6" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓

8. At the Depth of : 1400

9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Yelahanka Sub Division
(BBMP Ynk. Zn)
Yelahanka, Bangalore

Manager / Proprietor